



### Impact of Beachface Geomorphology on Salt Marsh Flushing in Singleton Swash, Myrtle Beach

#### Rick Peterson<sup>1</sup>, Rich Viso<sup>1</sup>, Matt Carter<sup>1</sup>, and Tom Gerigan<sup>2</sup>

<sup>1</sup> School of Coastal and Marine Systems Science, Coastal Carolina University, Conway, SC

<sup>2</sup> Stormwater Division, Horry County, Conway, SC


#### Monitoring Site

Beach Camera

### **CCU Beach Camera Website**



#### Webcam at the Sands Beach Club - Overlooking Singleton Swash



Click on the image for the full 8 megapixel shot... updated every 10 minutes

Image Average and Vanance

ASTAL CAROLINA LINIVERS

http://www.video-monitoring.com/beachcams/coastalcarolina/singletonswash/





## Hurricane Irene - August 27th, 2011

2011-08-26 15:23:29.187

2011-08-26 16:07:40.000

2011-08-26 16:51:35.906


2011-08-26 17:37:08.265

### Hurricane Irene - August 27th, 2011







### Withers Swash following a storm



#### 2013 Singleton Swash Monitoring






#### 2013 Singleton Swash Monitoring


#### Before Channel Straightening

# After Channel Straightening











## Steps Forward for Continued Study...

1.Bi-monthly RTK GPS surveys of the beachface and channel elevation

2.Georectify beachcam images for comparison to RTK surveys

3.Weekly (low-tide) surveys of water quality parameters along swash channel

4.Groundwater tracer sampling

5.Phytoplankton monitoring and identification screening

### Acknowledgements

 Funding provided by Horry County, Stormwater Division
Fieldwork assistance provided by Clay McCoy, Michael Slattery, Brian Johnson, Leigha Peterson, Kelly Gregorcyk, and Scott Kindelberger

